

# PRELIMINARY

## Approved Class HI Shock Testing Machines NAVSEAINST 9491.1D

NOTE: Facilities highlighted in green indicates that the machine(s) need to be recertified. To update any information here, please contact Daniel Lin at (215) 897-1127 or [daniel.lin@navy.mil](mailto:daniel.lin@navy.mil).

Please treat this document as unclassified!

| Company   | Point of Contact A  | Email Address A  | State | C/G | LWSM | # |
|---|---------------------|--|-------|-----|------|---|
|   |                     |  |       |     | MWSM | # |
| Address Mailing<br>Address (If Applicable)                                      | Point of Contact B  | Email Address B  |       |     | FSP  | # |
|   |                     |  |       |     | LFSP | # |
|   |                     |  |       |     | PWTV | # |
|   |                     |  |       |     | IFSP | # |
|   |                     |  |       |     | EFSP | # |
|   |                     |  |       |     | LBIM | # |
| National Technical Systems Huntsville Operations                                |                     |  | AL    | C   | LWSM | 1 |
| 7800 Highway 20 West<br>Huntsville, AL 35806                                    |                     |  |       |     | MWSM |   |
|   |                     |  |       |     | FSP  |   |
|   |                     |  |       |     | LFSP |   |
|   |                     |  |       |     | PWTV |   |
|   |                     |  |       |     | IFSP |   |
|   |                     |  |       |     | EFSP |   |
|   |                     |  |       |     | LBIM |   |
| Electronic Proving Ground<br>Ft. Huachuca                                       | Byron Alexander     | byron.alexander@conus.army.mil<br>(520) 538-3927<br>(520) 538-3935 | AZ    | G   | LWSM | 1 |
| 2000 Arizona Street<br>Office Stop: TEDT-EP-OPP<br>Fort Huachuca, AZ 85613-7063 |                     |  |       |     | MWSM | 0 |
|   |                     |  |       |     | FSP  | 0 |
|   |                     |  |       |     | LFSP | 0 |
|   |                     |  |       |     | PWTV | 0 |
|   |                     |  |       |     | IFSP | 0 |
|   |                     |  |       |     | EFSP | 0 |
|   |                     |  |       |     | LBIM | 0 |
| Honeywell International<br>Aircraft Accessories & Landing Systems               | Bill Tabor          | bill.tabor@honeywell.com<br>(480) 592-4341<br>(480) 592-4906       | AZ    | C   | LWSM | 1 |
| 1300 West Warner Road<br>Tempe, AZ 85284  |                     |  |       |     | MWSM | 0 |
|   |                     |  |       |     | FSP  | 0 |
|   |                     |  |       |     | LFSP | 0 |
|   |                     |  |       |     | PWTV | 0 |
|   |                     |  |       |     | IFSP | 0 |
|   |                     |  |       |     | EFSP | 0 |
|   |                     |  |       |     | LBIM | 0 |
| Sargent Controls and Aerospace  | Glenn Levey, x446   | gleve@sargentcontrols.com<br>(520) 744-1000<br>(520) 744-7529      | AZ    | C   | LWSM | 1 |
| 5675 West Burlingame Road<br>Tucson, AZ 85743                                   |                     |  |       |     | MWSM | 0 |
|   |                     |  |       |     | FSP  | 0 |
|   |                     |  |       |     | LFSP | 0 |
|   |                     |  |       |     | PWTV | 0 |
|   |                     |  |       |     | IFSP | 0 |
|   |                     |  |       |     | EFSP | 0 |
|   |                     |  |       |     | LBIM | 0 |
|   | Gary Tardivel, x416 | gtard@sargentcontrols.com<br>(520) 744-1000<br>(520) 744-7529      |       |     |      |   |

Please treat this document as unclassified!

|   |                |  |    |   |      |   |
|---|----------------|--|----|---|------|---|
| National Technical Systems<br>Highland Industrial Park<br>Building K-5<br>Camden, AR 71701<br>PO Box 3315<br>Camden, AR 71711 | Irv Williams   | irv.williams@ntscorp.com<br>(870) 574-0031<br>(870) 574-0037 | AR | C | LWSM | 1 |
|   |                |  |    |   | MWSM | 0 |
|   |                |  |    |   | FSP  | 0 |
|   |                |  |    |   | LFSP | 0 |
|   |                |  |    |   | PWTV | 0 |
|   |                |  |    |   | IFSP | 0 |
|   |                |  |    |   | EFSP | 0 |
|   |                |  |    |   | LBIM | 0 |
| Environment Associates, Inc.<br><br>9604 Variel Avenue<br>Chatsworth, CA 91311  | Robert Coiteux | bob@eatest.com<br>(818) 709-0568<br>(818) 709-8914           | CA | C | LWSM | 1 |
|   |                |  |    |   | MWSM | 0 |
|   |                |  |    |   | FSP  | 0 |
|   |                |  |    |   | LFSP | 0 |
|   |                |  |    |   | PWTV | 0 |
|   |                |  |    |   | IFSP | 0 |
|   |                |  |    |   | EFSP | 0 |
|   |                |  |    |   | LBIM | 0 |
| Garwood Laboratories<br><br>7829 Industry Avenue<br>Pico Rivera, CA 90660   | Don Bennett    | don.bennett@us.stork.com<br>(562) 949-2727<br>(562) 949-8757 | CA | C | LWSM | 1 |
|   |                |  |    |   | MWSM | 0 |
|   |                |  |    |   | FSP  | 0 |
|   |                |  |    |   | LFSP | 0 |
|   |                |  |    |   | PWTV | 0 |
|   |                |  |    |   | IFSP | 0 |
|   |                |  |    |   | EFSP | 0 |
|   |                |  |    |   | LBIM | 0 |
| National Technical Systems Fullerton Division<br><br>1536 East Valencia Drive<br>Fullerton, CA 92831                          | Rathish Rao    | rathishr@ntscorp.com<br>(714) 897-6110<br>(714) 897-6117     | CA | C | LWSM | 1 |
|   |                |  |    |   | MWSM | 0 |
|   |                |  |    |   | FSP  | 0 |
|   |                |  |    |   | LFSP | 0 |
|   |                |  |    |   | PWTV | 0 |
|   |                |  |    |   | IFSP | 0 |
|   |                |  |    |   | EFSP | 0 |
|   |                |  |    |   | LBIM | 0 |
| SPAWAR, San Diego<br><br>Code 2634<br>San Diego, CA 92152   | John Maltby    | john.maltby@navy.mil<br>(619) 553-1176<br>(619) 524-3736     | CA | G | LWSM | 1 |
|   |                |  |    |   | MWSM | 1 |
|   |                |  |    |   | FSP  | 0 |
|   |                |  |    |   | LFSP | 0 |
|   |                |  |    |   | PWTV | 0 |
|   |                |  |    |   | IFSP | 0 |
|   |                |  |    |   | EFSP | 0 |
|   |                |  |    |   | LBIM | 0 |

Please treat this document as unclassified!

|  |                |   |    |   |      |   |
|--|----------------|---|----|---|------|---|
| Wyle Laboratories, Norco<br><br>1841 Hillside Ave<br>Norco, CA 92860   | Phil Knoll     | (909) 382-2360  | CA | C | LWSM | 1 |
|  |                |   |    |   | MWSM | 1 |
|  |                |   |    |   | FSP  | 0 |
|  |                |   |    |   | LFSP | 0 |
|  |                |   |    |   | PWTV | 0 |
|  |                |   |    |   | IFSP | 0 |
|  |                |   |    |   | EFSP | 0 |
|  |                |   |    |   | LBIM | 0 |
| Sun Microsystems<br>Advanced Product Testing<br>1601 Dry Creek Drive<br>Suite 2000<br>Longmont, CO 80503             | Jerry Kimmel   | gerald_kimmel@aptesting.com<br>(303) 661-4827<br>(303) 673-7658 | CO | C | LWSM | 1 |
|  |                |   |    |   | MWSM | 0 |
|  |                |   |    |   | FSP  | 0 |
|  |                |   |    |   | LFSP | 0 |
|  |                |   |    |   | PWTV | 0 |
|  |                |   |    |   | IFSP | 0 |
|  |                |   |    |   | EFSP | 0 |
|  |                |   |    |   | LBIM | 0 |
| Ashcroft, Inc.<br><br>250 East Main Street<br>Stratford, CT 06497  | Phil Reed      | phil_reed@ashcroft.com<br>(203) 385-0318<br>(203) 385-0662      | CT | C | LWSM | 1 |
|  |                |   |    |   | MWSM | 0 |
|  |                |   |    |   | FSP  | 0 |
|  |                |   |    |   | LFSP | 0 |
|  |                |   |    |   | PWTV | 0 |
|  |                |   |    |   | IFSP | 0 |
|  |                |   |    |   | EFSP | 0 |
|  |                |   |    |   | LBIM | 0 |
| General Dynamics Corporation<br>Electric Boat Company<br>Department 431<br>75 Eastern Point Road<br>Groton, CT 06340 | Gerry Cosgrove | gcosgrov@gdeb.com<br>(860) 867-4455<br>(860) 433-1307           | CT | C | LWSM | 1 |
|  |                |   |    |   | MWSM | 1 |
|  |                |   |    |   | FSP  | 0 |
|  |                |   |    |   | LFSP | 0 |
|  |                |   |    |   | PWTV | 0 |
|  |                |   |    |   | IFSP | 0 |
|  |                |   |    |   | EFSP | 0 |
|  |                |   |    |   | LBIM | 0 |
| Stanford Technologies<br><br>57 Poplar Street<br>Glen Brook, CT 06906  | Jerry Ciccone  | stctestlab@aol.com<br>(203) 348-4080<br>(203) 327-5225          | CT | C | LWSM | 1 |
|  |                |   |    |   | MWSM | 0 |
|  |                |   |    |   | FSP  | 0 |
|  |                |   |    |   | LFSP | 0 |
|  |                |   |    |   | PWTV | 0 |
|  |                |   |    |   | IFSP | 0 |
|  |                |   |    |   | EFSP | 0 |
|  |                |   |    |   | LBIM | 0 |

Please treat this document as unclassified!

|  |                  |  |    |   |      |   |
|--|------------------|--|----|---|------|---|
| Ward Leonard Electric Company, Inc<br>401 Watertown Road<br>Thomaston, CT 06787                              | Myron Moroz      | mmoroz@wardleonard.com<br>(860) 283-5801 x114<br>(860) 283-5777    | CT | C | LWSM | 1 |
|  | Gary Konicki     | gkonicki@wardleonard.com<br>(860) 283-5801<br>(860) 283-5777       |    |   | MWSM | 0 |
|  |                  |  |    |   | FSP  | 0 |
|  |                  |  |    |   | LFSP | 0 |
|  |                  |  |    |   | PWTV | 0 |
|  |                  |  |    |   | IFSP | 0 |
|  |                  |  |    |   | EFSP | 0 |
|  |                  |  |    |   | LBIM | 0 |
| East-West Technology Corporation<br>15814 Corporate Circle<br>Jupiter, FL 33478                              | David Lichtman   | dave.lichtman@us.stork.com<br>(561) 776-7339<br>(561) 776-7344     | FL | C | LWSM | 1 |
|  | Karl Reimers     | karl.reimers@us.stork.com<br>(561) 776-7339<br>(561) 776-7344      |    |   | MWSM | 0 |
|  |                  |  |    |   | FSP  | 0 |
|  |                  |  |    |   | LFSP | 0 |
|  |                  |  |    |   | PWTV | 0 |
|  |                  |  |    |   | IFSP | 0 |
|  |                  |  |    |   | EFSP | 0 |
|  |                  |  |    |   | LBIM | 0 |
| Naval Surface Warfare Center (NSWC)<br>Panama City<br>Code L11<br>110 Vernon Avenue<br>Panama City, FL 32407 | William Fontaine | jeffrey.w.blankenshi@navy.mil(850) 234-4781 DSN: 436(850) 234-7019 | FL | G | LWSM | 1 |
|  | Jeff Blankenship |  |    |   | MWSM | 0 |
|  |                  |  |    |   | FSP  | 0 |
|  |                  |  |    |   | LFSP | 0 |
|  |                  |  |    |   | PWTV | 0 |
|  |                  |  |    |   | IFSP | 0 |
|  |                  |  |    |   | EFSP | 0 |
|  |                  |  |    |   | LBIM | 0 |
| QualTest, Inc.<br>5325 Old Winter Garden Road<br>Orlando, FL 32811   | Jim Gaudio       | jgaudio@qualtest.com<br>(407) 293-5844<br>(407) 297-7376           | FL | C | LWSM | 1 |
|  | Todd Scarborough | tscarborough@qualtest.com<br>(407) 293-5844<br>(407) 297-7376      |    |   | MWSM | 0 |
|  |                  |  |    |   | FSP  | 0 |
|  |                  |  |    |   | LFSP | 0 |
|  |                  |  |    |   | PWTV | 0 |
|  |                  |  |    |   | IFSP | 0 |
|  |                  |  |    |   | EFSP | 0 |
|  |                  |  |    |   | LBIM | 0 |
| Raytheon Company, St. Petersburg<br>1501 72nd Street North<br>St. Petersburg, FL 33733                       | B.L. Dabney      | bl_dabney@raytheon.com<br>(407) 293-2957<br>(727) 302-4882         | FL | C | LWSM | 1 |
|  | Michael McHale   | michael_r_mchale@raytheon.com<br>(407) 293-2957<br>(727) 302-4882  |    |   | MWSM | 0 |
|  |                  |  |    |   | FSP  | 0 |
|  |                  |  |    |   | LFSP | 0 |
|  |                  |  |    |   | PWTV | 0 |
|  |                  |  |    |   | IFSP | 0 |
|  |                  |  |    |   | EFSP | 0 |
|  |                  |  |    |   | LBIM | 0 |

Please treat this document as unclassified!

|   |                  |  |    |   |      |   |
|---|------------------|--|----|---|------|---|
| Delta Industries, Inc.  | Mark Price       | dindustries1@qwest.net<br>(208) 529-8545<br>(208) 529-8579       | ID | C | LWSM | 1 |
| 1490 Lindsay Boulevard<br>Idaho Falls, ID 83402                                 | John Price       | dindustries1@qwest.net<br>(208) 529-8545<br>(208) 529-8579       |    |   | MWSM | 0 |
|   |                  |  |    |   | FSP  | 0 |
| PO Box 50128<br>Idaho Falls, ID 83405   |                  |  |    |   | LFSP | 0 |
|   |                  |  |    |   | PWTV | 0 |
|   |                  |  |    |   | IFSP | 0 |
|   |                  |  |    |   | EFSP | 0 |
| LBIM  | 0                |  |    |   |      |   |
| Naval Surface Warfare Center (NSWC)<br>Crane Division                           | Michael E. Jones | michael.jones1@navy.mil<br>(812) 854-6973<br>(812) 854-2944      | IN | G | LWSM | 1 |
| 300 Highway 361<br>Building 3284<br>Code 4055<br>Crane, IN 47522                |                  |  |    |   | MWSM | 1 |
|   |                  |  |    |   | FSP  | 0 |
|   |                  |  |    |   | LFSP | 0 |
|   |                  |  |    |   | PWTV | 0 |
|   |                  |  |    |   | IFSP | 0 |
|   |                  |  |    |   | EFSP | 0 |
| LBIM  | 0                |  |    |   |      |   |
| Raytheon Technical Services Company, LLC  | Joe Hentz        | bobby_s_smith@raytheon.com(317) 306-7970 DSN: 369(317) 306-4949  | IN | C | LWSM | 1 |
| 6125 East 21st Street<br>Indianapolis, IN 46219                                 | Bobby Smith      |  |    |   | MWSM | 1 |
|   |                  |  |    |   | FSP  | 0 |
|   |                  |  |    |   | LFSP | 0 |
|   |                  |  |    |   | PWTV | 0 |
|   |                  |  |    |   | IFSP | 0 |
|   |                  |  |    |   | EFSP | 0 |
| LBIM  | 0                |  |    |   |      |   |
| Rockwell International Corporation Collins Avionics &<br>Communication Division | Tom Lehmkuhl     | tjlrhmku@rockwellcollins.com<br>(319) 263-0754<br>(319) 295-0654 | IA | C | LWSM | 1 |
| 350 Collins Road<br>Cedar Rapids, IA 52498                                      | Tim Steinbach    | tmsteinb@rockwellcollins.com<br>(319) 295-9091<br>(319) 295-0654 |    |   | MWSM | 0 |
|   |                  |  |    |   | FSP  | 0 |
|   |                  |  |    |   | LFSP | 0 |
|   |                  |  |    |   | PWTV | 0 |
|   |                  |  |    |   | IFSP | 0 |
|   |                  |  |    |   | EFSP | 0 |
| LBIM  | 0                |  |    |   |      |   |
| MET Laboratories, Inc.  | Johnnie Evans    | jevans@metlabs.com<br>(410) 949-1929<br>(410) 354-3313           | MD | C | LWSM | 1 |
| 914 W. Patapsco Ave.<br>Baltimore, MD 21230                                     | Allan Kimani     | akimani@metlabs.com<br>(410) 949-1826<br>(410) 354-3313          |    |   | MWSM | 0 |
|   |                  |  |    |   | FSP  | 0 |
|   |                  |  |    |   | LFSP | 0 |
|   |                  |  |    |   | PWTV | 0 |
|   |                  |  |    |   | IFSP | 0 |
|   |                  |  |    |   | EFSP | 0 |
| LBIM  | 0                |  |    |   |      |   |

Please treat this document as unclassified!

|   |  |  |           |   |      |   |
|---|--|--|-----------|---|------|---|
| Naval Air Warfare Center (NAWC)<br>Aircraft Division, Saint Inigoes<br>Environmental Lab<br>Building 8009<br>Code 44.5.12<br>Saint Inigoes, MD 20684  | Lou Schlosser  | richard.schlosser@navy.mil<br>(301) 862-8041<br>(301) 862-8193     | MD        | G   | LWSM | 1 |
|   | Gary Wood  | gary.k.wood@navy.mil<br>(301) 862-8041<br>(301) 862-8193           |           |   | MWSM | 0 |
| Naval Surface Warfare Center (NSWC)<br>Carderock Division - WB<br>For Information/Scheduling<br>Underwater Explosions Research Development<br>9500 MacArthur Boulevard<br>Bethesda, MD 20819<br>Aberdeen Test Center, Aberdeen Proving Ground<br>Aberdeen, MD 21005 |  |  | Joe Venne | joseph.venne@navy.mil<br>(301) 227-3955<br>(301) 227-5702 | MD   | G |
|   | LFSP   | 0  |           |   |      |   |
|   | PWTV   | 0  |           |   |      |   |
|   | IFSP   | 0  |           |   |      |   |
|   | EFSP   | 0  |           |   |      |   |
|   | LBIM   | 0  |           |   |      |   |
| BAE Systems<br>Armament Systems Division<br>4800 East River Road<br>Minneapolis, MN 55421   | Andy Anderson  | andy.l.anderson@baesystems.com<br>(763) 572-7177<br>(763) 572-4912 | MN        | C   | LWSM | 1 |
|   |  |  |           |   | MWSM | 1 |
|   |  |  |           |   | FSP  | 0 |
|   |  |  |           |   | LFSP | 0 |
|   |  |  |           |   | PWTV | 0 |
|   |  |  |           |   | IFSP | 0 |
| Ingalls Shipbuilding<br>PO Box 149<br>Pascagoula, MS 39568  | Sean Murphy  | sean.murphy@hii-ingalls.com<br>(228) 935-2284                      | MS        | C   | LWSM | 1 |
|   |  |  |           |   | MWSM | 0 |
|   |  |  |           |   | FSP  | 0 |
|   |  |  |           |   | LFSP | 0 |
|   |  |  |           |   | PWTV | 0 |
|   |  |  |           |   | IFSP | 0 |
| Portsmouth Naval Shipyard<br>Equipment Testing Laboratory<br>Code 270.4<br>Building 240<br>Portsmouth, NH 03804   | Andre Clavette   | clavetteat@mail.ports.navy.mil<br>(207) 438-5898<br>(207) 438-3413 | NH        | G   | LWSM | 2 |
|   |  |  |           |   | MWSM | 0 |
|   |  |  |           |   | FSP  | 0 |
|   |  |  |           |   | LFSP | 0 |
|   |  |  |           |   | PWTV | 0 |
|   |  |  |           |   | IFSP | 0 |
| Roy Pelkey  | pelkeyrn@mail.ports.navy.mil<br>(207) 438-3210<br>(207) 438-3413 | EFSP   | 0         |   |      |   |
|   |  | LBIM   | 0         |   |      |   |

Please treat this document as unclassified!

|  |               |  |    |   |      |      |   |      |   |
|--|---------------|--|----|---|------|------|---|------|---|
| NU Laboratories  | Bill Ferry    | (908) 713-9300 x115<br>(908) 713-9001                        | NJ | C | LWSM | 1    |   |      |   |
| 312 Old Allerton Road<br>Annandale, NJ 08801                               | Steve Baroczi | sbaroczi@nulabs.com<br>(908) 713-9300 x105<br>(908) 713-9001 | NJ |   | C    | MWSM | 1 |      |   |
|  |               |  |    |   |      | FSP  | 0 |      |   |
|  |               |  |    |   |      |      |   | LFSP | 0 |
|  |               |  |    |   |      |      |   | PWTV | 0 |
|  |               |  |    |   |      |      |   | IFSP | 0 |
|  |               |  |    |   |      |      |   | EFSP | 0 |
|  |               |  |    |   |      |      |   | LBIM | 0 |
|  |               |  |    |   |      |      |   |      |   |
| Naval Air Warfare Center (NAWC), Lakehurst                                 | Rob Ropes     | robert.ropes@navy.mil<br>(732) 323-7055<br>(732) 323-2125    | NJ | G | LWSM | 1    |   |      |   |
| Route 547<br>Code 4.8.3.4<br>Building 678, Room 112<br>Lakehurst, NJ 08733 | Steve Borders | steven.borders@navy.mil<br>(732) 323-7055<br>(732) 323-2125  | NJ |   | G    | MWSM | 0 |      |   |
|  |               |  |    |   |      | FSP  | 0 |      |   |
|  |               |  |    |   |      |      |   | LFSP | 0 |
|  |               |  |    |   |      |      |   | PWTV | 0 |
|  |               |  |    |   |      |      |   | IFSP | 0 |
|  |               |  |    |   |      |      |   | EFSP | 0 |
|  |               |  |    |   |      |      |   | LBIM | 0 |
|  |               |  |    |   |      |      |   |      |   |
| Tektronix  | Matt Wood     | matt.wood@tektronix.com<br>(973) 628-1363<br>(973) 628-7884  | NJ | C | LWSM | 1    |   |      |   |
| 1133 Route 23 South C<br>Wayne, NJ 07470                                   | Don Zoon      | don.zoon@tektronix.com<br>(973) 628-1363<br>(973) 628-7884   | NJ |   | C    | MWSM |   |      |   |
|  |               |  |    |   |      | FSP  |   |      |   |
|  |               |  |    |   |      |      |   | LFSP |   |
|  |               |  |    |   |      |      |   | PWTV |   |
|  |               |  |    |   |      |      |   | IFSP |   |
|  |               |  |    |   |      |      |   | EFSP |   |
|  |               |  |    |   |      |      |   | LBIM |   |
|  |               |  |    |   |      |      |   |      |   |
| Aero-Nav Laboratories, Inc   | Tony Phekoo   | tony@aeronavlabs.com<br>(718) 939-4422<br>(718) 539-3719     | NY | C | LWSM | 1    |   |      |   |
| 14-29 112th Street<br>College Point, NY 11356                              | Joe Osburn    | jro@aeronavlabs.com<br>(718) 939-4422<br>(718) 539-3719      | NY |   | C    | MWSM | 1 |      |   |
|  |               |  |    |   |      | FSP  | 0 |      |   |
|  |               |  |    |   |      |      |   | LFSP | 0 |
|  |               |  |    |   |      |      |   | PWTV | 0 |
|  |               |  |    |   |      |      |   | IFSP | 0 |
|  |               |  |    |   |      |      |   | EFSP | 0 |
|  |               |  |    |   |      |      |   | LBIM | 0 |
|  |               |  |    |   |      |      |   |      |   |
| American Environments Company, Inc.  | Kip Molnar    | kip@aeco.com<br>(631) 736-5883<br>(631) 736-5272             | NY | C | LWSM | 1    |   |      |   |
| 17 Commercial Boulevard<br>Medford, NY 11763                               | Wayne Miller  | test@aeco.com<br>(631) 736-5883<br>(631) 736-5272            | NY |   | C    | MWSM | 0 |      |   |
|  |               |  |    |   |      | FSP  | 0 |      |   |
|  |               |  |    |   |      |      |   | LFSP | 0 |
|  |               |  |    |   |      |      |   | PWTV | 0 |
|  |               |  |    |   |      |      |   | IFSP | 0 |
|  |               |  |    |   |      |      |   | EFSP | 0 |
|  |               |  |    |   |      |      |   | LBIM | 0 |
|  |               |  |    |   |      |      |   |      |   |



Please treat this document as unclassified!

|   |               |   |    |   |      |   |
|---|---------------|---|----|---|------|---|
| Dayton T. Brown, Inc.                             | Bob Ufer      | rufer@dtb.com<br>(631) 244-6388<br>(631) 589-3648             | NY | C | LWSM | 1 |
| 1175 Church Street<br>Bohemia, NY 11716           | Steve Benza   | sbenza@dtb.com<br>(631) 244-6388<br>(631) 589-3648            | NY | C | MWSM | 1 |
|   |               |   |    |   | FSP  | 0 |
|   |               |   |    |   | LFSP | 0 |
|   |               |   |    |   | PWTV | 0 |
|   |               |   |    |   | IFSP | 0 |
|   |               |   |    |   | EFSP | 0 |
|   |               |   |    |   | LBIM | 0 |
|   |               |   |    |   |      |   |
| Dynalec Corporation                               | David Neese   | dneese@dynalec.com<br>(315) 483-6923<br>(315) 483-2298        | NY | C | LWSM | 1 |
| 87 West Main Street<br>Sodus, NY 14551            | Frank Daratt  | fdaratt@dynalec.com<br>(315) 483-6923<br>(315) 483-2298       | NY | C | MWSM | 0 |
|   |               |   |    |   | FSP  | 0 |
| PO 188<br>Sodus, NY 14551                         |               |   |    |   | LFSP | 0 |
|   |               |   |    |   | PWTV | 0 |
|   |               |   |    |   | IFSP | 0 |
|   |               |   |    |   | EFSP | 0 |
|   |               |   |    |   | LBIM | 0 |
|   |               |   |    |   |      |   |
| Espey Manufacturing and Electronics Corporation   | George Sloan  | gsloan@espey.com<br>(518) 584-4100<br>(518) 245-4421          | NY | C | LWSM | 1 |
| 233 Ballston Avenue<br>Saratoga Springs, NY 12866 | Alan Winslow  | awinslow@espey.com<br>(518) 584-4100<br>(518) 245-4421        | NY | C | MWSM | 0 |
|   |               |   |    |   | FSP  | 0 |
|   |               |   |    |   | LFSP | 0 |
|   |               |   |    |   | PWTV | 0 |
|   |               |   |    |   | IFSP | 0 |
|   |               |   |    |   | EFSP | 0 |
|   |               |   |    |   | LBIM | 0 |
|   |               |   |    |   |      |   |
| New York Testing Laboratories                     | Nagesh Goel   | nageshtli@yahoo.com<br>(914) 471-1888<br>(908) 862-4825       | NY | C | LWSM | 1 |
| 47 Hudson Street<br>Ossining, NY 10562            | Kaspal Thomma | thumma_k@testwelllabs.com<br>(914) 944-2555<br>(914) 762-9638 | NY | C | MWSM | 0 |
|   |               |   |    |   | FSP  | 0 |
|   |               |   |    |   | LFSP | 0 |
|   |               |   |    |   | PWTV | 0 |
|   |               |   |    |   | IFSP | 0 |
|   |               |   |    |   | EFSP | 0 |
|   |               |   |    |   | LBIM | 0 |
|   |               |   |    |   |      |   |
| Retlif Testing Laboratories                       | Mike Bozza    | (631) 737-1500 x19<br>(631) 737-1497                          | NY | C | LWSM | 1 |
| 795 Marconi Avenue<br>Ronkonkoma, NY 11779        | Scott Poggi   | spoggi@retlif.com<br>(631) 737-1500 x31<br>(631) 737-1497     | NY | C | MWSM | 0 |
|   |               |   |    |   | FSP  | 0 |
|   |               |   |    |   | LFSP | 0 |
|   |               |   |    |   | PWTV | 0 |
|   |               |   |    |   | IFSP | 0 |
|   |               |   |    |   | EFSP | 0 |
|   |               |   |    |   | LBIM | 0 |
|   |               |   |    |   |      |   |

Please treat this document as unclassified!

|   |  |   |  |                                  |      |   |      |          |                |
|---|--|---|--|----------------------------------|------|---|------|----------|----------------|
| Westwood Corporation<br><br>12402 East 60th Street<br>Tulsa, OK 74146   | Larry Jensen   | larry.jessen@l-3com.com<br>(918) 250-4449<br>(918) 252-0486 | OK   | C                                | LWSM | 1 |      |          |                |
|   | John Morgan  | john.morgan@l-3com.com<br>(918) 250-4449<br>(918) 252-0486  |  |                                  | MWSM | 0 |      |          |                |
| Clark Dynamic Test Laboratory<br>The Clark Group<br>1801 Route 51 South<br>Jefferson Hills, PA 15025  |  |   | John Antenucci   | (412) 382-7173<br>(412) 382-4927 | PA   | C | FSP  | 0        |                |
|   | Secretary  | (412) 384-4300<br>(412) 382-4927                            |  |                                  |      |   | LFSP | 0        |                |
|   |  |   |  |                                  |      |   | PWTV | 0        |                |
|   |  |   | IFSP   | 0                                |      |   |      |          |                |
|   | Eaton Corporation<br><br>1 Tuscarawas Road<br>Beaver, PA 15009 | Bruce Campbell  | brucegcampbell@eaton.com<br>(724) 773-1204<br>(724) 773-1314 | PA                               |      |   | C    | EFSP     | 0              |
|   |  |   |  |                                  |      |   |      | Test Lab | (724) 773-1393 |
| LWSM  | 1  |   |  |                                  |      |   |      |          |                |
| MWSM  | 0  |   |  |                                  |      |   |      |          |                |
| FSP   | 0  |   |  |                                  |      |   |      |          |                |
| LFSP  | 0  |   |  |                                  |      |   |      |          |                |
| L-3 Communications<br>SPD Electrical Systems<br>13500 Roosevelt Boulevard<br>Philadelphia, PA 19116   | Chris Frantz   | chris.frantz@l-3com.com<br>(215) 698-6414<br>(215) 677-1504 | PA   | C                                | PWTV | 0 |      |          |                |
|   | Jack Woertz  | jack.woertz@l-3com.com<br>(215) 698-6361<br>(215) 677-1504  |  |                                  | IFSP | 0 |      |          |                |
| EFSP  |  |   | 0  |                                  |      |   |      |          |                |
| LBIM  |  |   | 0  |                                  |      |   |      |          |                |
| LWSM  |  |   | 1  |                                  |      |   |      |          |                |
| MWSM  |  |   | 0  |                                  |      |   |      |          |                |
| Naval Surface Warfare Center (NSWC)<br>Carderock Division - PNBC<br>Philadelphia Naval Business Center<br>Code 954<br>5001 South Broad Street<br>Philadelphia, PA 19112 | Drew Napolitan   | drew.napolitan@navy.mil<br>(215) 897-1146<br>(215) 897-8778 | PA   | G                                | FSP  | 0 |      |          |                |
|   | Long Nguyen  | long.nguyen@navy.mil<br>(215) 897-1146<br>(215) 897-8778    |  |                                  | LFSP | 0 |      |          |                |
| PWTV  |  |   | 0  |                                  |      |   |      |          |                |
| IFSP  |  |   | 0  |                                  |      |   |      |          |                |
| EFSP  |  |   | 0  |                                  |      |   |      |          |                |
| LBIM  |  |   | 0  |                                  |      |   |      |          |                |

Please treat this document as unclassified!

|   |                  |   |    |   |      |   |
|---|------------------|---|----|---|------|---|
| Naval Undersea Warfare Center (NUWC)  | Jerry Messina    | messinagi@npt.nuwc.navy.mil<br>(401) 832-5375<br>(401) 832-1544     | RI | G | LWSM | 1 |
| Code 72<br>Newport, RI 02841  | Al Jagaczewski   | jagaczewskiaj@npt.nuwc.navy.mil<br>(401) 832-5375<br>(401) 832-1544 |    |   | MWSM | 1 |
|   |                  |   |    |   | FSP  | 0 |
|   |                  |   |    |   | LFSP | 0 |
|   |                  |   |    |   | PWTV | 0 |
|   |                  |   |    |   | IFSP | 0 |
|   |                  |   |    |   | EFSP | 0 |
|   |                  |   |    |   | LBIM | 1 |
| SPAWAR Systems Center Charleston  | Lee Hinson       | tommy.hinson@navy.mil<br>(843) 218-4889<br>(843) 218-4841           | SC | G | LWSM | 1 |
| Radial Test and Evaluation Lab<br>Building 3413, Code 321<br>North Charleston, SC 29419 | Mike Harrington  | edward.harrington@navy.mil<br>(843) 218-4271<br>(843) 218-4841      |    |   | MWSM | 0 |
|   |                  |   |    |   | FSP  | 0 |
|   |                  |   |    |   | LFSP | 0 |
|   |                  |   |    |   | PWTV | 0 |
|   |                  |   |    |   | IFSP | 0 |
|   |                  |   |    |   | EFSP | 0 |
|   |                  |   |    |   | LBIM | 0 |
| Raytheon Company, McKinney  | Mark Taylor      | marktaylor@raytheon.com<br>(972) 952-4484<br>(972) 952-3206         | TX | C | LWSM | 1 |
| 2501 West University Avenue<br>McKinney, TX 75071                                       | Larry Taylor     | l_taylor8@raytheon.com<br>(972) 952-4484<br>(972) 952-3206          |    |   | MWSM | 0 |
|   |                  |   |    |   | FSP  | 0 |
|   |                  |   |    |   | LFSP | 0 |
|   |                  |   |    |   | PWTV | 0 |
|   |                  |   |    |   | IFSP | 0 |
|   |                  |   |    |   | EFSP | 0 |
|   |                  |   |    |   | LBIM | 0 |
| E-Laboratories, Inc.  | Ernie Letterie   | eletterie@e-labsinc.com<br>(540) 834-0372<br>(540) 834-8373         | VA | C | LWSM | 1 |
| 5150 Lad land Drive<br>Fredericksburg, VA   |                  |   |    |   | MWSM | 0 |
|   |                  |   |    |   | FSP  | 0 |
|   |                  |   |    |   | LFSP | 0 |
|   |                  |   |    |   | PWTV | 0 |
|   |                  |   |    |   | IFSP | 0 |
|   |                  |   |    |   | EFSP | 0 |
|   |                  |   |    |   | LBIM | 0 |
| Hi-Test Laboratories, Inc.  | Steve McCampbell | steve.mccampbell@hitestlabs.com<br>(434) 581-3204<br>(434) 581-3305 | VA | C | LWSM | 1 |
| 1104 Arvon Road<br>Arvon, VA 23004  | Bill Yancey      | bill.yancey@hitestlabs.com<br>(434) 581-3204<br>(434) 581-3305      |    |   | MWSM | 1 |
|   |                  |   |    |   | FSP  | 4 |
|   |                  |   |    |   | LFSP | 0 |
|   |                  |   |    |   | PWTV | 1 |
|   |                  |   |    |   | IFSP | 1 |
|   |                  |   |    |   | EFSP | 0 |
|   |                  |   |    |   | LBIM | 0 |

Please treat this document as unclassified!

|   |                   |  |    |   |      |   |
|---|-------------------|--|----|---|------|---|
| Lockheed Martin Manassas<br><br>Building 115<br>9500 Godwin Drive<br>Manassas, VA 20110   | Eric R. Johnson   | e.r.johnson@lmco.com<br>(703) 367-2515<br>(703) 367-2392           | VA | C | LWSM | 0 |
|   | Dave Boyer        | david.boyer@lmco.com<br>(703) 367-2515<br>(703) 367-2392           |    |   | MWSM | 1 |
| National Technical Systems Rustburg Division<br><br>3915 Sunnymeade Road<br>Rustburg, VA 24588<br>mailing<br>PO BOX 494 Intersection state Rt 669 & 660<br>Rustburg, VA 24588 | Calvin Milam      | calvin.milam@ntscorp.com<br>(434) 846-0244<br>(434) 846-2197       | VA | C | FSP  | 0 |
|   | Steve Thompson    | steve.thompson@ntscorp.com<br>(434) 846-0244<br>(434) 846-2197     |    |   | LFSP | 0 |
| Naval Surface Warfare Center (NSWC)<br>Dahlgren Division<br><br>Code G65<br>17320 Dahlgren Road<br>Dahlgren, VA 22448   | Luke Martin       | luke.a.martin@navy.mil<br>(540) 653-5646<br>(540) 653-0511         | VA | G | PWTV | 0 |
|   | George Clotfelter | george.e.clotfelter@navy.mil<br>(540) 653-3012<br>(540) 653-0511   |    |   | IFSP | 0 |
| Newport News Shipbuilding & Drydock Company<br><br>4101 Washington Avenue<br>Newport News, VA 23607   | Clarence Snyder   | earl.snyder@ngc.com<br>(757) 380-7936<br>(757) 688-6022            | VA | C | EFSP | 0 |
|   |                   |  |    |   | LBIM | 0 |
| Northrup Grumman<br>Sperry Marine<br><br>1070 Seminole Trail<br>Charlottesville, VA 22901   | Wayne Hotchkiss   | Wayne.Hotchkiss@sperry.ngc.com<br>(434) 974-2000<br>(434) 974-2259 | VA | C | LWSM | 1 |
|   |                   |  |    |   | MWSM | 0 |
|   |                   |  |    |   | FSP  | 0 |
|   |                   |  |    |   | LFSP | 0 |
|   |                   |  |    |   | PWTV | 0 |
|   |                   |  |    |   | IFSP | 0 |
|   |                   |  |    |   | EFSP | 0 |
|   |                   |  |    |   | LBIM | 0 |

Please treat this document as unclassified!

|   |                   |  |     |   |      |   |
|---|-------------------|--|-----|---|------|---|
| Trident LLC<br>USJ Division<br>435 Essex Avenue<br>Waynesboro, VA 22980                   | Joe Reisinger     | Joe.Reisinger@TridentLLC.com<br>(434) 220-8572<br>(434) 220-8509 | VA  | C | LWSM | 0 |
|   |                   |  |     |   | MWSM | 1 |
|   |                   |  |     |   | FSP  | 0 |
|   |                   |  |     |   | LFSP | 0 |
|   |                   |  |     |   | PWTV | 0 |
|   |                   |  |     |   | IFSP | 0 |
|   |                   |  |     |   | EFSP | 0 |
|   |                   |  |     |   | LBIM | 0 |
| NUWC Keyport<br>610 Dowell Street<br>Keyport, WA 98345                                    | Mark Reinhold     | mark.reinhold@navy.mil<br>(360) 396-2057<br>(360) 396-2123       | WA  | G | LWSM | 1 |
|   |                   |  |     |   | MWSM |   |
|   |                   |  |     |   | FSP  |   |
|   |                   |  |     |   | LFSP |   |
|   |                   |  |     |   | PWTV |   |
|   |                   |  |     |   | IFSP |   |
|   |                   |  |     |   | EFSP |   |
|   |                   |  |     |   | LBIM |   |
| Schweitzer Engineering Laboratories<br>2350 NE Hopkins Court<br>Pullman, WA 99163         | Carolyn Hicklin   | carolyn_hicklin@selgs.com<br>(509) 336-2411<br>(509) 336-2406    | WA  | C | LWSM | 1 |
|   |                   |  |     |   | MWSM | 0 |
|   |                   |  |     |   | FSP  | 0 |
|   |                   |  |     |   | LFSP | 0 |
|   |                   |  |     |   | PWTV | 0 |
|   |                   |  |     |   | IFSP | 0 |
|   |                   |  |     |   | EFSP | 0 |
|   |                   |  |     |   | LBIM | 0 |
| DRS Power and Control Technologies, Inc.<br>4265 North 30th Street<br>Milwaukee, WI 53216 | John Bong         | johnebong@drs-pct.com<br>NONE<br>(414) 449-7880                  | WI  | C | LWSM | 1 |
|   |                   |  |     |   | MWSM | 0 |
|   |                   |  |     |   | FSP  | 0 |
|   |                   |  |     |   | LFSP | 0 |
|   |                   |  |     |   | PWTV | 0 |
|   |                   |  |     |   | IFSP | 0 |
|   |                   |  |     |   | EFSP | 0 |
|   |                   |  |     |   | LBIM | 0 |
| CETENA S.p.A.<br>Via Erasmo Piaggio 161<br>16037 - Riga Trigoso<br>Genova, Italy          | Pasquale Calcagno | calcagno@cetena.it<br>011-39-010-5995489<br>011-39-335-8488960   | ITA | C | LWSM | 0 |
|   |                   |  |     |   | MWSM | 1 |
|   |                   |  |     |   | FSP  | 0 |
|   |                   |  |     |   | LFSP | 0 |
|   |                   |  |     |   | PWTV | 0 |
|   |                   |  |     |   | IFSP | 0 |
|   |                   |  |     |   | EFSP | 0 |
|   |                   |  |     |   | LBIM | 0 |

Please treat this document as unclassified!

|   |                    |   |     |   |      |   |
|---|--------------------|---|-----|---|------|---|
| Il Centro di Supporto e Sperimentazione Navale (C.S.S.N.<br>La Spezia)<br>Commanding Officer<br>Marine Militaire<br>Mariperman Facility<br>Viale San Bartolomeo 400<br>19138 La Spezia, Italy | Antonio Onorati    | antonio_onorati@marina.difesa.it<br>011-39-187-787825   | ITA | C | LWSM | 0 |
|   | Marco Venturini    | marco_venturini@persociv.difesa.it<br>011-39-187-787228 |     |   | MWSM | 1 |
|   |                    |   |     |   |      |   |
|   | LFSP               | 0   |     |   |      |   |
|   | PWTV               | 0   |     |   |      |   |
|   | IFSP               | 0   |     |   |      |   |
|   | EFSP               | 0   |     |   |      |   |
|   | LBIM               | 0   |     |   |      |   |
| INNOVACORP  | Neil Richter, x186 | Email Address<br>(902) 424-8670 x186<br>Fax Number      | CAN | C | LWSM | 1 |
| 101 Research Drive<br>Darthmouth, Nova Scotia B2Y4T6<br>CANADA  |                    |   |     |   |      |   |
|   |                    |   |     |   |      |   |
| LFSP  |                    |   |     |   | 0    |   |
| PWTV  |                    |   |     |   | 0    |   |
| IFSP  |                    |   |     |   | 0    |   |
| EFSP  |                    |   |     |   | 0    |   |
| LBIM  |                    |   |     |   | 0    |   |
| Naval Engineering Test Establishment  | David Bernier      | Email Address<br>(541) 366-4310<br>Fax Number           | CAN | G | LWSM | 1 |
| 9401 Wanklyn Street<br>LaSalle, Quebec H8R1Z2<br>CANADA   |                    |   |     |   |      |   |
|   |                    |   |     |   |      |   |
| LFSP  |                    |   |     |   | 0    |   |
| PWTV  |                    |   |     |   | 0    |   |
| IFSP  |                    |   |     |   | 0    |   |
| EFSP  |                    |   |     |   | 0    |   |
| LBIM  |                    |   |     |   | 0    |   |

# NOTES

Facilities highlighted in green indicates that the machines(s) needs to be re-certified.

To update any information here, please contact Dan Lin at NSWCCD (215) 897-1127 or email: [daniel.lin@navy.mil](mailto:daniel.lin@navy.mil).

Last updated: 23 Mar 2016

LWSM - Lightweight Shock Machine

MWSM - Medium Weight Shock Machine

FSP - Floating Shock Platform

LFSP - Large Floating Shock Platform

PWTV - Paddlewheel Test Vehicle

IFSP - Intermediate Floating Shock Platform

EFSP - Extended Floating Shock Platform

LBIM - Linear Biaxial Impact Machine